

SURVIVAL FACTORS ATTACHMENT

Fort Lauderdale Fire Rescue Incident Report

Fort Lauderdale, FL

HWY18FH013

(13 pages)

Incident Details

Incident Number: FFL18050800019080

Incident Status: Closed

Incident Date: 05/08/2018 18:46:19 Last Updated: 05/09/2018 12:59:16

INCIDENT INFORMATION

Incident Type Code: S25VF Incident Type Description: VEHICLE FIRE

Priority: 2 Incident Status: Closed

Created By Name: HAUBRICH, ROXANNE Created by Agency/Userid: COMM/BS11682

Modifying Circ: Dispositions: CL

Report Numbers: FL180018114 (FL/E49) (FL/E49)

Associated Incidents: FFL18050800019081, L3418050800072859, L3418050800072860

LOCATION INFORMATION

Location Name: Building:

Address: 1300 SEABREEZE BLVD Apartment:

City: FL Cross Street: 2700 HARBOR BEACH PKWY /

Area: 49 Sector:

Zone: 49 Reporting District:

Latitude: 26.10660043 **Longitude:** -80.10832860

CALLER INFORMATION

Caller Name: LARRY GROSHART Caller Phone Number:

Caller Location: Caller City:

Contact Caller: Yes Call Source: 0-NON 911 CALL

INCIDENT TIMES

EVENT:	DATE TIME:	AGENCY/USER:	DEVICE:	EVENT:	ELAPSED TIME:
ANI/ALI Received:				Call Received to Phone Pickup:	N/A
Phone Pickup:				Phone Pickup to Created:	N/A
Incident Created:	05/08/2018 18:46:19	COMM/BS11682	N35	Phone Pickup to 1st Dispatch:	N/A
1st Unit Dispatched:	05/08/2018 18:46:47	COMM/BS17163	C31	Created to 1st Dispatched:	00:00:28
1st Unit Enroute:	05/08/2018 18:48:04	COMM/BS17163	C31	1st Dispatch to 1st Enroute:	00:01:17
1st Unit Arrived:	05/08/2018 18:50:28	COMM/BS17094	C31	1st Enroute to 1st Arrived:	00:02:24
Route Closed:	05/09/2018 00:47:35	FL/E13	C31	Created to Closed:	06:01:16

ASSIGNED UNITS

Pri UNIT:	DISPATCH:	ENROUTE:	ARRIVE:	ENROUTE HOSPITAL:	ARRIVE HOSPITAL:	CLEAR:	DISPATCH TO CLEAR:	DISPO:
FL/BC13	05/08/2018 18:48:24	05/08/2018 18:48:30	05/08/2018 20:01:40			05/08/2018 20:34:42	01:46:18	
FL/DC2	05/08/2018 18:53:49					05/08/2018 18:56:43	00:02:54	
FL/E13	05/08/2018 18:48:21	05/08/2018 18:50:00	05/08/2018 18:55:21			05/08/2018 19:36:40	00:48:19	CL

FL/E13	05/08/2018 23:19:21	05/08/2018 23:21:29	05/08/2018 23:35:30			05/09/2018 00:47:35	01:28:14	CL
* FL/E49	05/08/2018 18:46:47	05/08/2018 18:48:04	05/08/2018 18:51:14			05/08/2018 20:34:35	01:47:48	
* FL/E49	05/08/2018 23:15:55					05/08/2018 23:19:43	00:03:48	
FL/FM2	05/08/2018 19:45:01	05/08/2018 19:45:06				05/08/2018 20:34:00	00:48:59	
FL/GP1FL	05/08/2018 18:54:22					05/08/2018 18:55:37	00:01:15	
FL/I6702	05/08/2018 18:54:26					05/08/2018 19:01:05	00:06:39	
FL/I8602	05/08/2018 19:01:05	05/08/2018 19:01:24	05/08/2018 19:28:56			05/08/2018 20:38:40	01:37:35	CL
FL/R13	05/08/2018 18:53:51	05/08/2018 18:55:28	05/08/2018 19:00:09			05/08/2018 19:39:37	00:45:46	
FL/R49	05/08/2018 18:47:04	05/08/2018 18:48:52	05/08/2018 18:50:28	05/08/2018 18:59:59	05/08/2018 19:05:06	05/08/2018 20:34:35	01:47:31	

ASSIGNED PERSONNEL					
UNIT:	OFFICERID:	OFFICER NAME:			
FL/BC13	BC13	BC13, BATTALION			
FL/DC2	DC2	DC2, DIVISION CHIEF			
FL/E13	E13	E13, ENGINE			
FL/E49	E49	E49, ENGINE			
FL/R13	R13	R13, RESCUE			
FL/R49	R49	R49, RESCUE			

INCIDENT COMMENTS					
DATE TIME:	USERID:	DEVICE:	COMMENTS:		
05/08/2018 18:46:19	BS11682	N35	VAN ON FIRE		
05/08/2018 18:46:37	BS11682	N35	VEH CRASHED INTO A WALL AND NOW ON FIRE		
05/08/2018 18:46:47	BS09571	N28	THIS IS ALSO A S4 WITH INJURIES		
05/08/2018 18:47:12	BS11682	N35	COMPL ADV NO BODY GOT OUT AND VEH ON FIRE		
05/08/2018 18:47:19	BS09571	N28	SOMEONE IS INSIDE THE VEH THAT IS ON FIRE		
05/08/2018 18:47:53	BS09571	N28	CALLER DISC FROM		
05/08/2018 18:47:55	BS09571	N28	NFI		
05/08/2018 18:48:02	BS18207	C38	34D14 ADV HAVE UNITS RESP CODE 3		
05/08/2018 18:48:12	BS11682	N35	COMPL CALLING FROM ONE HOUSE OVER		
05/08/2018 18:48:46	BS18207	C38	SAME AS 34/72859		
05/08/2018 18:49:02	BS18207	C38	VEH IS SLOWED INFLAMED		
05/08/2018 18:49:23	BS18201	N19	Dup: GRY TESLA ON FIREUNK IF OCCUPIEDENGULFED IN FIRE, HEARD AN EXPLOSION		
05/08/2018 18:49:24	BS18201	N19	Dup: GRY TESLA ON FIREUNK IF OCCUPIEDENGULFED IN FIRE, HEARD AN EXPLOSION		
05/08/2018 18:51:44	BS18207	C38	HARBOR BEACH PKWY / HOLIDAY DR REROUTE		
			PROBABY 2X THAT ARE STILL FILLY INFLAMED		
05/08/2018 18:51:58	BS18207	C38	34C19 COVERING HARBOR BEACH PKWY		

INCIDENT COMME	INCIDENT COMMENTS				
DATE TIME:	USERID:	DEVICE:	COMMENTS:		
05/08/2018 18:53:10	BS17163	C27	2 SIGNAL 7'S		
05/08/2018 18:53:12	BS18207	C38	AIR 1008		
05/08/2018 18:54:25	BS18207	C38	34C17 BLOCKING HARBOR BEACH		
05/08/2018 18:54:30	BS18207	C38	34E22 1048 REF S7		
05/08/2018 18:55:00	BS18207	C38	DO MITCHELL 1048		
05/08/2018 18:56:07	BS17635	C20	I6702 IS NEXT UP I8602 IS ALREADY ON A DIFFERENT CALL		
05/08/2018 18:56:57	BS17449	C21	SHORT AND LONG FORM GROUP PAGE COMPLETE		
05/08/2018 18:58:30	BS18207	C38	34C20 HOLIDAY / SEABREEZE DIRECTING S73		
05/08/2018 18:59:18	BS17163	C27	1 ADULT LEVEL 2		
05/08/2018 18:59:46	BS18207	C38	34C32 WILL BE AT TURN AROUND FOR S73		
05/08/2018 19:02:57	BS18207	C38	34E22 ADV TO HAVE ADDTL UNITS RESP CODE 3		
05/08/2018 19:03:55	BS12411	C36	BOLOED ON D3		
05/08/2018 19:04:05	BS18207	C38	34E22 ADV HOMICIDE 1048		
05/08/2018 19:04:19	BS18207	C38	AIR 1003 REF UNITS RESPONDING CODE 3		
05/08/2018 19:04:46	BS18207	C38	34C14 ADV LET NO ONE THROUGH		
05/08/2018 19:05:46	BS18207	C38	34C71 97 HARBOR / A1A		
05/08/2018 19:09:53	BS18207	C38	FAMILY MEMBER DROVE PASS 34C32 GOING 60 MPH		
05/08/2018 19:11:38	BS18207	C38	PER 34S36 HAVE 2X ADDTL UNITS COMING TO ASST WITH S73		
05/08/2018 19:13:27	BS18207	C38	34D14 AIR 1008		
05/08/2018 19:15:46	BS18207	C38	NORTH END COVERED FROM 1300		
05/08/2018 19:26:14	BS18207	C38	MEDIA IS 1097 PER 34A20		
05/08/2018 19:29:01	BS18207	C38	34E22 WILL HANDLE MEDIA		
05/08/2018 20:41:48	BS18207	C38	34D14 REQ A UNIT AT SUN / NE 14 AV		
05/08/2018 20:42:22	BS18207	C38	NE 15 AV / SUN **		
05/08/2018 20:57:37	BS18207	C38	REAR PASSENGER IS 1004 BREATHING / CONS PER 34Z14		
05/08/2018 22:09:45	BS18207	C38	< 34D17 IS REQ RESC TO MAKE IT TO S/4 1020 TO OPEN DOOR FOR VEH >		
05/08/2018 23:15:49	BS17094	C31	Reopen: PER BC13		
05/08/2018 23:30:10	BS14522	C38	34C19 SUPP TAKEN		
05/08/2018 23:36:37	BS17141	C01	< EDUARDO HAUSER REQ AN OFC ASSIGNED TO CASE 1045 HIM. ADV HE IS FAMILY OF ONE OF THE VICTIMS. >		
05/08/2018 23:42:04	BS14522	C38	34C14 SUPP TAKEN		
05/09/2018 00:39:04	BS18502	C40	< ROBERT MOLLOY(DIRECTOR FOR OFFICER SAFETY) WANTS TO SPEAK TO A UNIT ABOUT THE S/4PHONE # ADV HE POSS WANT TO SEND INVESTIGATORS OUT TO THE SCENE >		
05/09/2018 00:40:50	BS14522	C38	10-23 AIR 10-3		
05/09/2018 00:42:05	BS14522	C38	34T16 10-48		
05/09/2018 01:06:31	BS14522	C38	<incid #:l3418050800072859="" 4i(25vf)="" incid="" type:=""></incid>		
05/09/2018 01:13:01	BS14522	C38	UNITS CAN OPEN UP TRAFFIC		

PRE-SCHEDULED INFORMATION

ADDRESS CHANGES		
PRIORITY CHANGES		
INCIDENT TYPE CHANGES		

Executed: 05/10/2018 10:27:20

Incident Report 2018-0818018114-000 Printed: 05/10/2018 08:25:14 Number of Pages: 8

2016-0616016114-000 Number of Pages. 6				
	Basic			
Alarm Date and Time	18:46:19 Tuesday, May 8, 2018			
Arrival Time	18:50:28			
Controlled Date and Time				
Last Unit Cleared Date and Time	00:47:35 Wednesday, May 9, 2018			
Response Time	0:04:09			
Priority Response	Yes			
Fire Department Station	49			
Shift	В			
Incident Type	13 - Mobile property (vehicle) fire			
Aid Given or Received	N - None			
Action Taken 1	11 - Extinguish			
Action Taken 2	00M - Triptix EMS PCR Generated under same alarm			
Action Taken 3	34 - Transport person			
Casualties	No			
Apparatus - Suppression	7			
Apparatus - EMS	2			
Apparatus - Other	1			
Personnel - Suppression Personnel	13			
Personnel - EMS Personnel	6			
Property Loss	\$50,000.00			
Contents Loss	\$500.00			
Property Value	\$50,000.00			
Contents Value	\$500.00			
Property Use	963 - Street or road in commercial area			
Location Type	Address			
Address	1300 SEABREEZE BLVD			
City, State Zip	FORT LAUDERDALE, FL 33316			
District	49			
Directions	1300 SEABREEZE BLVD			
Latitude	26.106600			
Longitude	-080.10832			
Map Page	0832			
	Situation			
Initial Dispatch Code	VEHICLE FIRE			
Final Dispatch Code	VEHICLE FIRE			
	Fire			
Area of Origin	83 - Engine area, running gear, wheel area			
Cause of Ignition	2 - Unintentional			
Mobile Equipment Involved	3 - Involved in ignition and burned			
Mobile Equipment Type	11 - Passenger car.			
Mobile Equipment State	FL			
	Apparatus - 16702			
Apparatus ID	16702			

Page 1 of 8 Printed: 05/10/2018 08:25:14

Incident Report 2018-0818018114-000 Printed: 05/10/2018 08:25:14 Number of Pages: 8

18-0818018114-000	Number of Pages: 8
	Apparatus - 16702
Apparatus Dispatch Date and Time	18:54:26 Tuesday, May 8, 2018
Apparatus Clear Date and Time	19:01:05 Tuesday, May 8, 2018
Apparatus priority response	Yes
Apparatus Use	1
Apparatus Type	00 - Other apparatus/resource
	Apparatus - FM2
Apparatus ID	FM2
Apparatus Dispatch Date and Time	19:45:01 Tuesday, May 8, 2018
En route to scene date and time	19:45:06 Tuesday, May 8, 2018
Apparatus Clear Date and Time	20:34:00 Tuesday, May 8, 2018
Apparatus priority response	Yes
Apparatus Use	1
Apparatus Type	00 - Other apparatus/resource
	Apparatus - R49
Apparatus ID	R49
Response Time	0:03:24
Apparatus Dispatch Date and Time	18:47:04 Tuesday, May 8, 2018
En route to scene date and time	18:48:52 Tuesday, May 8, 2018
Apparatus Arrival Date and Time	18:50:28 Tuesday, May 8, 2018
En route to facility date and time	18:59:59 Tuesday, May 8, 2018
Arrive facility date and time	19:05:06 Tuesday, May 8, 2018
Apparatus Clear Date and Time	20:34:35 Tuesday, May 8, 2018
Apparatus priority response	Yes
Number of People	3
Apparatus Use	2
Apparatus Type	71 - Rescue unit
Personnel 1	230601 - Williams, David
	Position: FF
Personnel 2	230737 - Melton, Daniel
	Position: FF
Personnel 3	230795 - Ilonta, Cosmin M
	Position: FF
	Apparatus - L49
Apparatus ID	L49
Response Time	0:04:09
Apparatus Dispatch Date and Time	18:46:19 Tuesday, May 8, 2018
En route to scene date and time	18:46:19 Tuesday, May 8, 2018
Apparatus Arrival Date and Time	18:50:28 Tuesday, May 8, 2018
Apparatus priority response	Yes
Number of People	3
Apparatus Use	1
Apparatus Action Taken 1	73 - Provide manpower
Apparatus Action Taken 2	00M - Triptix EMS PCR Generated under same alarm

Page 2 of 8 Printed: 05/10/2018 08:25:14

Incident Report 2018-0818018114-000 Printed: 05/10/2018 08:25:15 Number of Pages: 8

	Apparatus - L49
Apparatus Type	12 - Truck or aerial
Personnel 1	230634 - Chioffe, James
	Position: D/E
	Personnel Action Taken 1: 73 - Provide manpower
	Personnel Action Taken 2: 00M - Triptix EMS PCR Generated under same alarm
Personnel 2	230178 - Webster, Edward
	Position: CAPT
	Personnel Action Taken 1: 73 - Provide manpower
	Personnel Action Taken 2: 00M - Triptix EMS PCR Generated under same alarm
Personnel 3	230230 - Doerfler, Todd
	Position: FF
	Personnel Action Taken 1: 73 - Provide manpower
	Personnel Action Taken 2: 00M - Triptix EMS PCR Generated under same alarm

	Apparatus - E49
Apparatus ID	E49
Response Time	0:04:27
Apparatus Dispatch Date and Time	18:46:47 Tuesday, May 8, 2018
En route to scene date and time	18:48:04 Tuesday, May 8, 2018
Apparatus Arrival Date and Time	18:51:14 Tuesday, May 8, 2018
Apparatus Clear Date and Time	20:34:35 Tuesday, May 8, 2018
Apparatus priority response	Yes
Number of People	3
Apparatus Use	1
Apparatus Action Taken 1	11 - Extinguish
Apparatus Type	11 - Engine
Personnel 1	230430 - Fillyaw, Thomas E
	Position: FF
	Personnel Action Taken 1: 81 - Incident command
Personnel 2	230756 - Erb, Matthew A
	Position: D/E
	Personnel Action Taken 1: 11 - Extinguish
Personnel 3	230346 - Robertson, Chad
	Position: CAPT
	Personnel Action Taken 1: 11 - Extinguish

		Apparatus - BC13	
Apparatus ID	BC13		
Response Time	0:04:26		
Apparatus Dispatch Date and Time	18:48:24	Tuesday, May 8, 2018	
En route to scene date and time	18:48:30	Tuesday, May 8, 2018	
Apparatus Arrival Date and Time	18:52:50	Tuesday, May 8, 2018	
Apparatus Clear Date and Time	20:34:42	Tuesday, May 8, 2018	
Apparatus priority response	Yes	### (##)	
Number of People	1		
Apparatus Use	1		

Page 3 of 8 Printed: 05/10/2018 08:25:15

Incident Report 2018-0818018114-000 Printed: 05/10/2018 08:25:15 Number of Pages: 8

018-0818018114-000 Number of Pages: 8		
Apparatus - BC13		
Apparatus Action Taken 1	81 - Incident command	
Apparatus Type	92 - Chief officer car	
Personnel 1	230615 - Gollan, Stephen W	
	Position: BC	
	Apparatus - E13	
Apparatus ID	E13	
Response Time	0:07:00	
Apparatus Dispatch Date and Time	18:48:21 Tuesday, May 8, 2018	
En route to scene date and time	18:50:00 Tuesday, May 8, 2018	
Apparatus Arrival Date and Time	18:55:21 Tuesday, May 8, 2018	
Apparatus Clear Date and Time	19:36:40 Tuesday, May 8, 2018	
Apparatus priority response	Yes	
Number of People	3	
Apparatus Use	1	
Apparatus Type	11 - Engine	
Personnel 1	230161 - Arcas, David	
	Position: D/E	
Personnel 2	230214 - Maglietta, Carl	
	Position: FF	
Personnel 3	230280 - Pardo, Ricardo	
	Position: CAPT	
	Apparatus - R13	
Apparatus ID	R13	
Response Time	0:06:18	
Apparatus Dispatch Date and Time	18:53:51 Tuesday, May 8, 2018	
En route to scene date and time	18:55:28 Tuesday, May 8, 2018	
Apparatus Arrival Date and Time	19:00:09 Tuesday, May 8, 2018	
Apparatus Clear Date and Time	19:39:37 Tuesday, May 8, 2018	
Apparatus priority response	Yes	
Number of People		
	3	
Apparatus Use	2	
Apparatus Action Taken 1	2 86 - Investigate	
Apparatus Action Taken 1 Apparatus Type	2 86 - Investigate 71 - Rescue unit	
Apparatus Action Taken 1	2 86 - Investigate 71 - Rescue unit 230446 - Cortes, Christopher M	
Apparatus Action Taken 1 Apparatus Type	2 86 - Investigate 71 - Rescue unit 230446 - Cortes, Christopher M Position: FF	
Apparatus Action Taken 1 Apparatus Type Personnel 1	2 86 - Investigate 71 - Rescue unit 230446 - Cortes, Christopher M Position: FF Personnel Action Taken 1: 86 - Investigate	
Apparatus Action Taken 1 Apparatus Type	2 86 - Investigate 71 - Rescue unit 230446 - Cortes, Christopher M Position: FF Personnel Action Taken 1: 86 - Investigate 230656 - Perusi, Tracy D	
Apparatus Action Taken 1 Apparatus Type Personnel 1	2 86 - Investigate 71 - Rescue unit 230446 - Cortes, Christopher M Position: FF Personnel Action Taken 1: 86 - Investigate 230656 - Perusi, Tracy D Position: FF	
Apparatus Action Taken 1 Apparatus Type Personnel 1 Personnel 2	2 86 - Investigate 71 - Rescue unit 230446 - Cortes, Christopher M Position: FF Personnel Action Taken 1: 86 - Investigate 230656 - Perusi, Tracy D Position: FF Personnel Action Taken 1: 86 - Investigate	
Apparatus Action Taken 1 Apparatus Type Personnel 1	2 86 - Investigate 71 - Rescue unit 230446 - Cortes, Christopher M Position: FF Personnel Action Taken 1: 86 - Investigate 230656 - Perusi, Tracy D Position: FF	

Apparatus - 18602

Page 4 of 8 Printed: 05/10/2018 08:25:15

Incident Report 2018-0818018114-000 Printed: 05/10/2018 08:25:15 Number of Pages: 8

Apparatus - 18602			
Apparatus ID	18602		
Response Time	0:27:51		
Apparatus Dispatch Date and Time	19:01:05 Tuesday, May 8, 2018		
En route to scene date and time	19:01:24 Tuesday, May 8, 2018		
Apparatus Arrival Date and Time	19:28:56 Tuesday, May 8, 2018		
Apparatus Clear Date and Time	20:38:40 Tuesday, May 8, 2018		
Apparatus Use	0		
Apparatus Action Taken 1	80 - Information, investigation & enforcement, other		
Apparatus Type	00 - Other apparatus/resource		

Apparatus - E13		
Apparatus ID	E13	
Response Time	0:16:09	
Apparatus Dispatch Date and Time	23:19:21 Tuesday, May 8, 2018	
En route to scene date and time	23:21:29 Tuesday, May 8, 2018	
Apparatus Arrival Date and Time	23:35:30 Tuesday, May 8, 2018	
Apparatus Clear Date and Time	00:47:35 Wednesday, May 9, 2018	
Apparatus priority response	Yes	
Number of People	3	
Apparatus Use	1	
Apparatus Action Taken 1	73 - Provide manpower	
Apparatus Type	11 - Engine	
Personnel 1	230161 - Arcas, David	
	Position: D/E	
Personnel 2	230214 - Maglietta, Carl	
	Position: FF	
	Personnel Action Taken 1: 73 - Provide manpower	
Personnel 3	230280 - Pardo, Ricardo	
	Position: CAPT	
	Personnel Action Taken 1: 73 - Provide manpower	

Authority			
Reported By	·-·,		
Officer In Charge	·*•,		
Reviewer	-,		

	Narratives		
Na	arrative Name	R13	
Na	arrative Type	Company	
Na	arrative Date	22:35:29 Tuesday, May 8, 2018	
Αι	ithor	230318 - Cochran, Michael	
Au	ithor Rank	FF	
Au	thor Assignment	1	

Page 5 of 8 Printed: 05/10/2018 08:25:15

Incident Report 2018-0818018114-000 Printed: 05/10/2018 08:25:15 Number of Pages: 8

Narratives

Narrative Text Responded to car crash involving fire with occupants trapped. Arrived and staged medical

sector during operation. R13 without pt. contact. No injuries involving Fire / EMS

personael reported on scene.

Narrative Name L49
Narrative Type Company

Narrative Date 07:08:48 Wednesday, May 9, 2018

Author 230178 - Webster, Edward

Author Rank CAPT
Author Assignment 1

Narrative Text L49 responded to a reported MVA with vehicle on fire people entrapped. On arrival

assisted E49 with water

supply, Pt. evaluation and securing scene for electrical hazard after fire was extinguished.

Upon determination of two fatalities scene was secured for investigation.

Narrative Name E13
Narrative Type Company

Narrative Date 07:23:26 Wednesday, May 9, 2018

Author 230280 - Pardo, Ricardo

Author Rank CAPT
Author Assignment 1

Narrative Text E13 responded with a heavy traffic delay and assisted with manpower.

Narrative Name B13
Narrative Type Incident

Narrative Date 22:02:00 Wednesday, May 9, 2018

Author 230615 - Gollan, Stephen W

Author Rank BC Author Assignment 1

Narrative Text B13 self dispatched to reported vehicle fire with possible occupants trapped in 49 zone.

While en route B13 requested an additional Engine and Ladder be assigned to the call. R49 was the first to arrive and reported 1 vehicle with heavy damage completely engulfed

in flames.

Upon arrival, B13 established command and made contact with E49. E49 advised that they were starting fire attack utilizing foam from the 1 3/4 inch line on the front bumper. B13 assigned L49 to stretch a 5" supply line to the hydrant located approximately 150' to the north of E49.

As B13 approached the involved vehicle he noted that there was possibly 3 patients on the sidewalk. An additional rescue was requested and B13 assigned R49 to the male patient with obvious facial trauma. It was later determined that this was the only patient and the other 2 subjects were by standards. R49's patients was declared a level 2 trauma and transported to BGMC. (See Triptix).

B13 completed a 180 degree survey on the accessible side of the vehicle noting that there was various debris on the road way. The majority of fire was located to the front of the

Page 6 of 8 Printed: 05/10/2018 08:25:15

Incident Report 2018-0818018114-000 Printed: 05/10/2018 08:25:15 Number of Pages: 8

Narratives

vehicle and E49B was having difficulty extinguishing what appeared to be a battery located under the car in the area of the "A" post to where the right front tire would have been. A second battery cell was located approximately 10' to the west of the vehicle and occasionally sparking. A water foam mixture was utilized to extinguish the fire.

While fire attack was taking place, family members began to arrive. The Captain from E49 and 2 PD officers was sent to calm the family. At this same time E13 and R13 were both arriving on the north side of the incident. E13 was assigned to utilize scene tape and set up a perimeter to assist with evidence preservation for PD. E13 immediately began moving all by standers back to the north and south setting up fire line barrier at approximately 200' from the active incident. The Captain from E13 was requested to supervise fire attack.

B13 made contact with PD on scene and requested for additional PD units to close Seabreeze blvd from East lake Dr. to Harbor Dr in both directions. B13 also requested that Father Perkins respond to the scene to assist with family members

Upon R13 arrival, they were assigned to check for additional patients and determined that the 2 additional males on the sidewalk were bystanders and not injured. All of the vehicles in the surrounding area were checked and all parties denied injuries. R13 was then assigned to stage on the north side of the incident as medical/ rehab.

Once the fire was out and all hazards were mitigated B13 released all units from scene and requested that they return to their respective stations for debrief. E49 was requested by PD to remain on scene while THI completed photos. Once THI determined it was ok, E49 was sent back to their station to complete debrief with other units.

A couple of hours later E49 and B13 were requested back to the scene to assisted with removing the victims from the vehicle. The first victim was located in the drivers seat of the vehicle with no obvious entanglement hazards. E49 completed a door pop on the drivers side to assist with access to the victim. The second victim was located in the front passenger seat. The door on this side of the vehicle was already gone from the collision and fire. The area around the victim was inspected and no obvious entanglement or hazards appeared to be present. Both units cleared and returned to quarters.

At approximately 00:30 B13 received an additional call from Westway towing requesting for a unit to stand by while the victims were removed and the vehicle was placed on the flat bed. E13 and B13 responded back to the scene and assisted county coroner with removing the victims from the vehicle. E13 utilized a haligan to free debris around the second victims left foot. Once the victim was separated from the debris E13 removed him from the vehicle.

E13 then pulled the front bumper line and staged while the vehicle was loaded. As soon as the vehicle was moved the battery that was located under the "A" post on the passenger side began to spark and immediately caught fire. Foam and water once again utilized to extinguish the fire. The vehicle was then loaded without incident and transported by Westway. All units cleared and returned to quarters.

Page 7 of 8 Printed: 05/10/2018 08:25:15

Incident Report 2018-0818018114-000 Printed: 05/10/2018 08:25:15 Number of Pages: 8

Narratives

End of Report

Page 8 of 8 Printed: 05/10/2018 08:25:15