



Survival Factors Attachment:

Photographs

Crozet, Va.

HWY18MH005

(6 pages)



Photo #1: Exterior view of front of lead locomotive and damage caused by collision



Photo #2: Interior view of the locomotive front console area, engineer and fireman's seat



Photo #3: Interior view of rear seat in cab of lead locomotive



Photo #4: Interior view of rear cab area behind engineer console in lead locomotive



Photo #5: Exterior frontal view of trash truck at final rest



Photo #6: Rear view of detached trash truck hopper at final rest



Photo #7: Interior view of trash truck cab, displaced seat and computer terminal



Photo #8: Interior view of trash truck cab and shattered front windshield



Photo #9: Interior view of trash truck cab and deformation of rear wall and bench seat



Photo #10: Interior view of trash truck cab showing close-up of roof deformation