



Survival Factors Photos

**Penwell, Texas
HWY15FH004**

(6 pages)



Photo 1 – Frontal view of Bluebird bus showing front end torn away.



Photo 2 – Left side angle view of Bluebird bus showing missing front end and deformation to side from pillar impacts.



Photo 3 – View of rear caged wall showing bowing to center.



Photo 4 – View of rear jump-seat with seat belt webbing pulled out showing lack of blood.




Photo 5 – View of three tiny blood spots on rear jump-seat seat belt webbing.



Photo 6 – Overhead view of destroyed driver seat.



Photo 7 – View of collapsed front jump seat.



Photo 8 – View of deformation to steering wheel.



Photo 9 – View of indentation to back of seatback.