



Systems 9 - 747-SL-20-048 - Fig. 30. Wire bundle to the leading edge power drive unit sleeved in service.