



Systems 9 - 747-SL-20-048 - Fig. 4. Degraded raceway clamp cushion. The degraded portion of the clamp should be replaced to avoid subsequent damage.