



Systems 9 - 747-SL-20-048 - Fig. 5. Damaged cushion on a bundle clamp. Cushion can be damaged by mechanical forces or chemicals. Here no damage to the sleeving was observed.