



Systems 9 - Aging Aircraft Wire Testing - Photo 20.
Polyimide breakdown following Forced Hydrolysis.