



Systems 9 - Electrical Short Circuit/Arcing of Aged Aircraft Wiring - Figure 44. Test 20: Damage done in longitudinal abrasion tests with aluminum 7075