



Systems 9 - Exhibit No. 9B - Photo 10. Figure 10c. The stationary load contact of the SPR circuit breaker has a tarnished appearance. Arrow highlights the mechanical wear from the making and breaking of the contacts.