



Systems 9 - Exhibit No. 9B - Photo 14. Figure 14a. The left side of the scavenger pump switch indicating the knob had been displaced towards the right.