

Systems 9 - Exhibit No. 9B - Photo 14. Figure 14c. As received condition of the RTV circuit breaker. Upper arrow highlights the corroded terminal harware. Lower arrow highlights the cracked housing.