



Systems 9 - Exhibit No. 9B - Photo 15. Figure 15a. The environmental seal sleeve was displaced from the knob towards the "on" position.