



Systems 9 - Exhibit No. 9B - Photo 15. Figure 15c. The various mechanical components of the RTV circuit breaker are corroded. The moving contacts are lying against the stationary contacts.