



Systems 9 - Exhibit No. 9B - Photo 18. Figure 18c. The stationary load terminal and contact of the RTV circuit breaker have a tarnished appearance.