



Systems 9 - Exhibit No. 9B - Photo 24. Figure 24g. Compression damage from strain relief clamp (N93119 Fuel probe sample #5).