



Systems 9 - Exhibit No. 9B - Photo 3. Figure 3c. Various mechanical components of the SPR circuit breakers are corroded. The moving contacts are lying against the stationary contacts.