


Break in PTFE insulation from contact with terminal  
block serrated surface beneath clamp



Systems 9 - Exhibit No. 9B - Photo 34. Figure 34g. Fuel probe (model no. FG420A12, serial no. A-14) from N93105 with compression damage to PTFE insulation.