


**Damage to PTFE insulation from contact  
with terminal block serrated surface beneath  
steel clamp**



**0.1 inch**

**Systems 9 - Exhibit No. 9B - Photo 35. Figure 35g.  
Compensator (model no. FG6C1, serial no. B-162) from  
N93105 with compression damage to PTFE insulation.**