


Load Contact



Line Contact

3.1 mm

Systems 9 - Exhibit No. 9B - Photo 4. Figure 4c. The moving contacts of the SPR circuit breaker have a tarnished appearance. White arrows highlight the mechanical wear from the making and breaking of the contacts. Black indicates the fibrous residue.