

Systems 9 - Exhibit No. 9B - Photo 4. Figure 4g. Termincal block wiring. Wires are dressed differently and the strain relief clamp has been flattened (from N93105).