


PTFE insulation thinned and split through to the conductor



Cross-sectional view of compression damage. Section was taken where black film can be seen the insulation surface in Figure 42

0.016 inch

Systems 9 - Exhibit No. 9B - Photo 43. Figure 43g. Lo-Z wire from N93105 (model no. FG420A12, serial no. A-21).