


PTFE insulation
thinned from about
8.8 mils to about
3.9 mils in circled
area of Figure 46



0.016 inch

Systems 9 - Exhibit No. 9B - Photo 47. Figure 47g. Cross-sectional view of damaged Hi-Z pigtail lead wire from compensator (model no. FG6C2, serial no. Y-147) out of N93105.