



Systems 9 - Exhibit No. 9B - Photo 8. Figure 8c. The stationary load terminal and contact of the SPR circuit breaker have a tarnished appearance.