



Systems 9 - Fuel Quantity Indication System - Photo 10. Structure repairs from bottom of main deck cabin floor. Large green item is back side of STA 920 floor beam and visible are black sealant and red fasteners. The part oriented from upper left to lower