

STA 400
RIGHT
FWD SIDE

Systems 9 - Fuel Quantity Indication System - Photo 18. Detail of pencil and other markings on repair found in frame at station 400 (right), beneath route of W350 and W1360 wire bundles.