



Systems 9 - Fuel Quantity Indication System - Photo 28. Wire bundles from over cockpit floor, aft of right emergency exit. No features were found that provided an accurate orientation.