



P/N 60B92010-1

IC603C4

S/N 7152

Systems 9 - Fuel Quantity Indicators - Photo 18. Damaged indicator examined October 28, 1998, at Boeing EQA lab. Darkened yellow cover on transformer