



Systems 9 - Fuel Quantity Indicators - Photo 4. Totalizer (interior) pins 3 and 11, showing solder joints in near-contact (separated by crack). Straight silver wire behind the pins is .011 diameter and was added for