



Systems 9 - Fuel Quantity Indicators - Photo 5. Totalizer (pins 3 and 11) after controlled power applications bridged the crack 3 times.