

747-400
FQIS

Systems 9 - Photo 1. Airplane 3. Drill shaving of 2.7 inch length, next to 3x5 inch card. Shaving found on right wing FQIS wires at wing/fuselage pressure seal in B-747-400.