



Systems 9 - Photo 18. Airplane 9. B-747 avionics rack wiring between stanchions and beneath drip shield. Metal shavings and lint coat the area. Raceway clamp is missing retainer at right.