



Systems 9 - Photo 29. Airplane 13. B-747 station 400 (left) opening with clamp loosened for photo. Arrow points to hole worn through black woven sleeve on wires. Wire in sleeve was damaged. Loose string ties visible. Clamp above is missing retainer.