



Systems 9 - Photo 42. Airplane 19. B767 detail of burned area of vertical wire bundles. The adjacent burned bundle (to left) had molten holes in wire insulation and was more than an inch away. Wire types were Aromatic Polyimide and XL-ETFE.