



Systems 9 - Photo 47. Airplane 19. B-757 Compensator and wire insulation. Roughened wire insulation was found where wires contacted the corners of the can shaped lower portion and near the row of rivets. (Top of compensator shown to right).