

Beechcraft



Hawker

TEXTRON AVIATION

March 21, 2019

**IN REPLY REFER TO:
L-175-19-016**

Brent Allen
Aviation Safety Investigator
Federal Aviation Administration
[REDACTED]
Fargo, ND 58104

**RE: 1980 Cessna 550; Serial number: 550-0146; REG: N941JM
Location: Fargo, ND; D/A: 11-30-18**

Dear Mr. Allen,

I have reviewed your recent email correspondence to Textron Aviation's Air Safety Investigations Department. The toilet installation depicted in the photographs you provided appear to match Textron Aviation's non-flushing toilet design for the aircraft model involved in the above-referenced accident. Textron Aviation's installation of that toilet design does not include any type of seat belt. In addition, Textron Aviation does not have any service documents that match the toilet seat belt installation depicted in the photographs.

If further assistance is required, please contact me or another member of our Air Safety Investigations Department.

Sincerely,

[REDACTED]
William B. Welch, Ed.D
Manager, Air Safety Investigations
Textron Aviation