DEPARTMENT OF TRANSPORTATION

FEDERAL RAILROAD ADMINISTRATION (FRA)

INSPECTION REPORT

OMB Approval No.: 2130-0509

Inspector's Name				Inspector's Signature							Ins	pector's ID No.	Report N). L	Date			
				NATHAN AARON WOLFE			Digitally signed by NATHAN AARON WOLFE DN: c=US, o=U.S. Government, ou=FRA FRAdtlantaGA, ou=DOT FRAdtlantaGA, cn=NATHAN AARON WOLFE Date: 2018.02.08 15:3:225-05'00'							уу	mm	dd		
Wolfe, Nathan												33		2018	02	08		
Railroad/Company Name & Address							R/C	2	Divisi	ion		RR/Co. Re	o. Representative (Receipt Acknowledged)					
CSX TRANSPORTATION						1	R	FLO	REN		Name	CHRIS B	UMG	ARDNE	R			
500 TAYLOR STREET						RR/0	Co	I LO	KL1V		-							
								e e	Subdivision			Title	ASSISTANT DIVISION ENGINEER					
CAYCE SC			29033				CS	Х	COLUMBIA Email			Email						
50			27035								Signature							
												Signature						
From: City CAYCE	Codes 0370)	Destinat	ion City o	& Cou	nty	Ci			Codes	From Latitude							
State SC			45		City	CAYCI	E		03			0370	From Longitude					
County LEXINGT	C06	3	County	LEXIN	GTO	N	C0			C063	To Latitude							
Mile Post: From S	85.60 Inspection Point			nt COL	UMBIA SUBDIVISION RECOF						To Longitude							
Activity						PECTION												
Code:	TREC																	
Units:	inits: 1																	
Sub Units: 21																		
Item Initials/Milepost Equipment/Track #			Type/Kind 49 CFR		V Defect S		ule			Speed	Class	Train #/Site	<u> </u> s	NFR*	RCL**	# of	Activity	
				USC						Speed	Ciabb	i i uni i i o i u			Inc.	Occ.***	Code	
1														N	Ν	0		
Description - [** Comment to Railroad/Company **]																		
Track inspection re	Track inspection records between the dates of $1/4/18$ and $2/4/18$ did not reveal any exceptions for required frequency or traversal of main or siding tracks on the															he		
Columbia Subdivision. The last main track inspection through the Amtrak P091 accident near MP S367.1 was made by CSX Roadmaster Phillip Logan on $2/2/18$ with no defects noted. The last walking inspection of the Silica Siding track was made by CSX Track Inspector Antonio Folk on $1/23/18$ with (1) rail joint missing (2) bolts																		
no defects noted. The found and repaired	he last walk	ing inspection	n of the Silic	a Sidin	g track v	was mae	de by	CSX T	rack I	nspector	r Anto	onio Folk on Storege gravit	1/23/18 wit	h (1) :	rail joint	missing	(2) bolts	
Antonio Folk on 1/3								ing and	inoru	I Auto P	amp	Storage Switt	clies were li	laue t	Jy CSA	Tack Ins	pector	
Seal Applied Seal Rem				*				Hazard Class				U	UN/NA ID					
Violation Recommended Yes		Yes	No			I	Latitude:					Longitude:						
Written Notification to FRA of Remedial Action is:		l 🗸 Option	✓ Optional R		Railroad Action Co		e Date(mi			n/dd/y	/yyyy):			Comments on back?				