

INSPECTION REPORT

Inspector's Name Roberts, David G		Inspector's Signature			Inspector's ID No. 73880	Report No. 80	Date yy mm dd 2016 06 29						
Railroad/Company Name & Address BURLINGTON NORTHERN SANTA FE 200 EAST ATCHISON PAMPA TX 79065				R/C R	Division KANSAS	RR/Co. Representative (Receipt Acknowledged) Name John Thomas Title ROADMASTER Email Signature _____							
From: City PANHANDLE		Codes 5200	Destination City & County			Codes	From Latitude						
State TX		48	City PANHANDLE			5200	From Longitude						
County CARSON		C065	County CARSON			C065	To Latitude						
Mile Post: From 0526.11		To 0526.11	Inspection Point MAIN TRACK ONE			To Longitude							
Activity Code:	TOM	RWP	MTW										
Units:	1	1	1										
Sub Units:	0	1	0										
Item	Initials/Milepost	Equipment/Track #	Type/Kind	49 CFR/USC	Defect	Subrule	Speed	Class	Train #/Site	SNFR*	RCL**	# of Occ.***	Activity Code
1										N	N	0	
Description - [** Comment to Railroad/Company **] No defects written for accident investigation on 3260 East Switch													
Seal Applied			Seal Removed			Hazard Class			UN/NA ID				
Violation Recommended				<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		Latitude:			Longitude:				
Written Notification to FRA of Remedial Action is:				<input type="checkbox"/> Required <input checked="" type="checkbox"/> Optional		Railroad Action Code		Date(mm/dd/yyyy):		Comments on back?			