

NTSB Docket Item
DCA-05-MR-009
Metrolink Derailment
Glendale, California
January 26, 2005

Track Inspection Reports

**(RAILROAD)
TRACK INSPECTION REPORT**

DIVISION SCAX	DISTRICT Valley	MAIN OR BRANCH NAME 111	DATE 1-2-05
TRACK SEW. SID. CR. YD. =	CLASS 1-4	BETWEEN M.P. 76.6	AND M.P. 3.5

TURNOUTS, RAILROAD CROSSING, AND GRADE

CROSSINGS INSPECTED BETWEEN M.P.

AND M.P.

DEFECT NOTED	LOCATION	REMEDIAL ACTION TAKEN
	H. La. Rd Valley sub between end of	
	Track and CP BURLING JCT. And on the	
	#1 RAT between CP BURLING JCT and CP	
	TAYLOR	
NONE		
	Sidings	
NONE	VINCENT	
 	CAVENNA	
NONE	LARG	
BROKEN BOLT	Humphrey 538.7	replaced broken bolt
NONE	SARGUS	
 	NEWBALL	
 	Sylmar	
 	SUN VALLEY	
NONE	BRIGHTON	

INSPECTED BY



TITLE

Insp.

P. more

**(RAILROAD)
TRACK INSPECTION REPORT**

DIVISION <i>SAK</i>	DISTRICT <i>Valley</i>	MAIN OR BRANCH NAME <i>1st</i>	DATE <i>1.3.0</i>
TRACK SEW. SIG. OR YD.	CLASS <i>1-4</i>	BETWEEN M.P.	AND M.P. <i>28.0</i>

TURNOUTS, RAILROAD CROSSING, AND GRADE

CROSSINGS INSPECTED BETWEEN M.P.

AND M.P.

DEFECT NOTED	LOCATION	REMEDIAL ACTION TAKEN
<i>Performed special track inspection due to bad weather. ON THE MAIN TRACK BETWEEN 21.00 AND 21.05</i>	<i>Stations not on list.</i>	
<i>NONE</i>		
<i>None</i>	<i>Sidings</i>	
<i>NONE</i>	<i>VINCENT</i>	
<i>1</i>	<i>LEWIS</i>	
<i>NONE</i>	<i>1.000</i>	
<i>broken 21.05</i>	<i>Hampton 28.8</i>	<i>replaced with 1st Term.</i>
<i>NONE</i>	<i>JANUS</i>	
<i>1</i>	<i>Newhall</i>	<i>Timbered</i>
<i>1</i>	<i>Sylvan</i>	
<i>NONE</i>	<i>Sun Valley</i>	
	<i>Brighton</i>	<i>✓</i>
<i>215.255</i>		

INSPECTED BY

[Redacted Name]

TITLE *Inspector*

**(RAILROAD)
TRACK INSPECTION REPORT**

DIVISION SCAX	DISTRICT Valley	MAIN OR BRANCH NAME (K) # 1MT	DATE 1-4-05
TRACK SEW, SID, OR YD.	CLASS 1-4	BETWEEN M.P. 76.00	AND M.P. 3.05

TURNOUTS, RAILROAD CROSSING, AND GRADE

CROSSINGS INSPECTED BETWEEN M.P.

AND M.P.

DEFECT NOTED	LOCATION	REMEDIAL ACTION TAKEN
None	Siding	
None	VINCENT	
}	RAVENNA	TRAVELLED
	LANG	TRAVELLED
	Humphys	
	Saugus	
	New Hall	TRAVELLED
	Sylmar	
	SUN VALLEY	
	BRIGHTON	TRAVELLED

INSPECTED BY



TITLE **INSP.**

**(RAILROAD)
TRACK INSPECTION REPORT**

DIVISION SWAX	DISTRICT VALLEY 1	MAIN OR BRANCH NAME 117 2	DATE 1-7-05
TRACK SEW. SID. OR YD. -	CLASS 1-4	BETWEEN M.P. 7.66	AND M.P. 3.5

TURNOUTS, RAILROAD CROSSING, AND GRADE

CROSSINGS INSPECTED BETWEEN M.P.

AND M.P.

DEFECT NOTED	LOCATION	REMEDIAL ACTION TAKEN
Hi Railed	FACTORYS ON W. END	
Track between the END	of Track AND	
CP Burbank Junction AND on the		
# 2 between CP Burbank Jct. AND CP Taylor		
NONE		
	Sidings	
NONE	VINCENT	
	RAVENNA	
	LANE	
	Humphreys	
	Saugus	
	NEW HALL	Traversed
	Sylmar	Traversed
	Sun Valley	
	Brighton	

INSPECTED BY

[Redacted Name]

TITLE **INSP.**

(RAILROAD)
TRACK INSPECTION REPORT

DIVISION SCAX	DISTRICT Valley	MAIN OR BRANCH NAME 1 vt	DATE 1-8-05
TRACK SEW. SID. OR YD.	CLASS	BETWEEN M.P. 67.5	AND M.P. 23.8

TURNOUTS, RAILROAD CROSSING, AND GRADE

CROSSINGS INSPECTED BETWEEN M.P.

AND M.P.

DEFECT NOTED	LOCATION	REMEDIAL ACTION TAKEN
213, 239		
<p>Performed special Hi Rail inspection on the Valley Sub. between CP Harold AND CP Roxford due to heavy rains. No defects noted.</p>		

INSPECTED BY _____ TITLE **Insp.**

**(RAILROAD)
TRACK INSPECTION REPORT**

DIVISION <i>SCAX</i>	DISTRICT <i>Valley Sub</i>	MAIN OR BRANCH NAME <i>(V)</i>	DATE <i>1-9-05</i>
TRACK SEW/SID OR YD	CLASS <i>1-4</i>	BETWEEN M.P. <i>76.6</i>	AND M.P. <i>38.6</i>

TURNOUTS, RAILROAD CROSSING, AND GRADE

CROSSINGS INSPECTED BETWEEN M.P.

AND M.P.

DEFECT NOTED	LOCATION	REMEDIAL ACTION TAKEN
<i>Special inspection due to Storm watch under 213,239 from End of track to CP^{EC} Honey and back before Metrolink start running.</i>		
<i>213.33.07 Mud Slide MT</i>	<i>MP 42.9 East of CP Long</i>	<i>cleaning mud</i>

INSPECTED BY _____ TITLE *Insp.*

(RAILROAD)
TRACK INSPECTION REPORT

DIVISION <i>SCAX</i>	DISTRICT <i>Valley Sub</i>	MAIN OR BRANCH NAME <i>(V)</i>	DATE <i>1-11-05</i>
TRACK SEW/SID OR YD.	CLASS <i>1-4</i>	BETWEEN M.P. <i>76.6</i>	AND M.P. <i>23.6</i>

TURNOUTS, RAILROAD CROSSING, AND GRADE

CROSSINGS INSPECTED BETWEEN M.P. _____ AND M.P. _____

DEFECT NOTED	LOCATION	REMEDIAL ACTION TAKEN
<i>Special inspection due to heavy rain under track to</i>	<i>713, 239</i>	<i>from end of track to CP Roxford, 10 defects.</i>

INSPECTED BY *[REDACTED]* TITLE *Insp.*

**(RAILROAD)
TRACK INSPECTION REPORT**

DIVISION SCAX	DISTRICT Valley Sub	MAIN OR BRANCH NAME IV1	DATE 1-12-05
TRACK SEW(SID) OR TD.	CLASS 1-4	BETWEEN M.P. 3.5	AND M.P. 76.6

TURNOUTS, RAILROAD CROSSING, AND GRADE

CROSSINGS INSPECTED BETWEEN M.P.

AND M.P.

DEFECT NOTED	LOCATION	REMEDIAL ACTION TAKEN
None	Regular westward inspection from CP Taylor to CP Buybank JCT #1 MT, CP Buybank JCT to CP Portal MT, Siding CP Portal CP Hood, MT CP Hood to CP Honby Siding CP Honby CP Humphrys, MT CP Humphrys to End of track	
	Siding	
	Brighton	
	Sunvalley	
	Sylmar	
	Newhall	
	Burgos	
	Humphrys	
	Lang	
	Ruening	
	Vincent	

INSPECTED BY [REDACTED] TITLE **INSP.**

**(RAILROAD)
TRACK INSPECTION REPORT**

DIVISION SCA X	DISTRICT Valley Sub	MAIN OR BRANCH NAME 1V #1-2 MT	DATE 1-14-05
TRACK SEW SID OR YD.	CLASS 1-4	BETWEEN M.P. 76.4	AND M.P. 3.5

TURNOUTS, RAILROAD CROSSING, AND GRADE

CROSSINGS INSPECTED BETWEEN M.P.

AND M.P.

DEFECT NOTED	LOCATION	REMEDIAL ACTION TAKEN
none	Regular eastward inspection from end of track to CP Crest MT, siding CP Crest to CP Quartz, MT CP Quartz to CP Hood, siding CP Hood to CP Portal, MT CP Portal to CP Burbank JCT #1 MT from CP Burbank JCT to CP Taylor.	
none	Sidings Vincent Ravenna Lang Humphys Gaugus Newhall Sylmar Sun Valley Brighton	

INSPECTED BY

[REDACTED]

TITLE

insp

**(RAILROAD)
TRACK INSPECTION REPORT**

DIVISION 364X	DISTRICT Valley Sub	MAIN OR BRANCH NAME IRY#1+2MT	DATE 1-17-05
TRACK SEW/SID. OR YD.	CLASS 1-4	BETWEEN M.P. 76.6	AND M.P. 8.1

TURNOUTS, RAILROAD CROSSING, AND GRADE

CROSSINGS INSPECTED BETWEEN M.P.

AND M.P.

DEFECT NOTED	LOCATION	REMEDIAL ACTION TAKEN	
none ↓	Regular eastward inspection		
	from CP end of track to CP		
	crest, siding between CP crest		
	and CP Quartz, MT from CP		
	Quartz to CP Hood, siding		
	CP Hood to CP Portal, MT CP Portal		
	to CP Burbank OCT #1 MT from		
	CP Burbank OCT to CP Dayton		
	none	Sidings:	
	↓	Vincent	
	Ravena		
	Long		
	Humphrys		
	Saugus		
	Newhall		
	Sylmar		
	Sun Valley		
	Brighton		

INSPECTED BY [REDACTED] TITLE Insp.

**(RAILROAD)
TRACK INSPECTION REPORT**

DIVISION SGAX	DISTRICT Valley Sub	MAIN OR BRANCH NAME 1V#1+2 MT	DATE 1-19-05
TRACK SEW(S) OR YD.	CLASS 1-4	BETWEEN M.P. 3.5	AND M.P. 76.6

TURNOUTS, RAILROAD CROSSING, AND GRADE

CROSSINGS INSPECTED BETWEEN M.P.

AND M.P.

DEFECT NOTED	LOCATION	REMEDIAL ACTION TAKEN
}	Regular westward inspection from CP Taylor to CP Olive #1 MT.	
	Siding CP Olive to CP Brighton, MT	
	CP Brighton to CP Roxford,	
	Siding CP Roxford to CP Balboa,	
	MT CP Balboa to CP Ravenna, siding	
	CP Ravenna to CP Kocian, MT	
	CP Kocian to CP End of track	
213.3302	MP25.1 Drainage	Removing debris from obstructed by debris drainage.
none	Belings	
}	Brighton	
	Sunvalley	
	Sylmar	
	Newhall	
	Saugus	
	Humphrys	
	Lang	
	Ravenna	
	Vincent	

INSPECTED BY [REDACTED] TITLE Inspector

**(RAILROAD)
TRACK INSPECTION REPORT**

DIVISION SCAX	DISTRICT Valley sub	MAIN OR BRANCH NAME V #1 + 2 MT	DATE 1-21-05
TRACK SEW. AND/OR YD.	CLASS 1-4	BETWEEN M.P. 76.6	AND M.P. 2.1

TURNOUTS, RAILROAD CROSSING, AND GRADE
CROSSINGS INSPECTED BETWEEN M.P. _____ AND M.P. _____

DEFECT NOTED	LOCATION	REMEDIAL ACTION TAKEN
none	Regular eastward inspection From End of track to CP Humphrys MT, Siding CP Hum- phrys to CP Honby, MT from CP Honby to CP Sheldon, Siding CP Sheldon to CP Penrose, MT CP Penrose to CP Burbank JCT, #2 MT from CP Burbank JCT to CP Dayton.	
}	Sidings	
	Vincen-t	
	Ravenna	
	Lang	
	Humphrys	
	Saugus	
	Newhall	
	Sylmar	
Sunvalley		
Brighton		

INSPECTED BY [REDACTED] TITLE **Insp.**

**(RAILROAD)
TRACK INSPECTION REPORT**

DIVISION <i>SCAX</i>	DISTRICT <i>Valley Sub</i>	MAIN OR BRANCH NAME <i>1r1</i>	DATE <i>1-24-05</i>
TRACK SEW, SID, OR YD.	CLASS <i>1-4</i>	BETWEEN M.P. <i>76.6</i>	AND M.P. <i>53.9</i>

TURNOUTS, RAILROAD CROSSING, AND GRADE

CROSSINGS INSPECTED BETWEEN M.P.

AND M.P.

DEFECT NOTED	LOCATION	REMEDIAL ACTION TAKEN
	<i>H.-rail valley sub with</i>	
	<i>FRA inspector from CP</i>	
	<i>Sierra to CP Kocien on</i>	
	<i>M+</i>	
<i>63-07</i>	<i>MP 65.7 West</i>	<i>surfacing and</i>
<i>not out of class</i>	<i>of Barrel Spring</i>	<i>tamping</i>
<i>5/8 5/8 + 1/8</i>		
	<i>Measuring curves at MP 64.75</i>	
	<i>and 62.4 with M. Lang</i>	

INSPECTED BY ████████████████████ TITLE *Inspr.*

**(RAILROAD)
TRACK INSPECTION REPORT**

DIVISION SCAX	DISTRICT Valley sub	MAIN OR BRANCH NAME 1 R#1 + 2 MT	DATE 1-25-05
TRACK SEW(SID) OR YD.	CLASS 1-4	BETWEEN M.P. 3.5	AND M.P. 53.9

TURNOUTS, RAILROAD CROSSING, AND GRADE

CROSSINGS INSPECTED BETWEEN M.P.

AND M.P.

DEFECT NOTED	LOCATION	REMEDIAL ACTION TAKEN
none	Regular westward inspection from CP Taylor to CP Burbank JCT on #1 MT, CP Burbank JCT to CP Roxford on MT Siding CP Roxford to CP Bulboa, MT CP Bulboa to CP Honby, Siding CP Honby to CP Humphys, MT CP Humphys to CP Ravensong Siding CP Ravensong to CP Kouch.	
	Sidings:	
	Brighton	
	Sonvalley	
	Sylmer	
	Newhall	
	Sacrus	
	Humphys	
	Lang	
	Ravennag	
	Vincent	

INSPECTED BY [REDACTED] TITLE INSP

(RAILROAD)
TRACK INSPECTION REPORT

DIVISION <i>SEAY</i>	DISTRICT <i>Valley sub</i>	MAIN OR BRANCH NAME <i>(V)</i>	DATE <i>1-26-05</i>
TRACK SEW, SID, OR YD.	CLASS <i>1-4</i>	BETWEEN M.P. <i>12.7</i>	AND M.P. <i>62.2</i>

TURNOUTS, RAILROAD CROSSING, AND GRADE

CROSSINGS INSPECTED BETWEEN M.P.

AND M.P.

DEFECT NOTED	LOCATION	REMEDIAL ACTION TAKEN
<i>213.239 none</i>	<i>Special inspection due to rain from CP Brighton to CP Crest and back all the way on maint track because no trains at all</i>	

INSPECTED BY  TITLE *Insp*