

Rail Cut-Ins and Cut-Outs Report

From: 01/01/2015 To: 03/13/2017

Subdivision: ESTHERVILLE SUB

Records: 20

Subdivision	Segm	Track Type	MP	L/R Rail	Track Align.	Test Date	Orig. Length	Repaired Length	Defect Comment
ESTHERVILLE SUB	8268	SIMN	74.27	R	0	1/5/2015	0.5	0	
ESTHERVILLE SUB	8268	SIMN	71.19	R	0	2/26/2015	0.5	0	
ESTHERVILLE SUB	8254	SIMN	67.5	L	0	3/17/2015	-0.13	0	
ESTHERVILLE SUB	8253	SIMN	39.85	R	0	3/24/2015	2	0	
ESTHERVILLE SUB	8254	SIMN	70.43	L	0	5/5/2015	1.25	0	
ESTHERVILLE SUB	8254	SIMN	70.43	R	0	5/5/2015	1	0	
ESTHERVILLE SUB	8254	SIMN	70.4	R	0	5/8/2015	-0.5	0	
ESTHERVILLE SUB	8254	SIMN	70.43	L	0	5/8/2015	-1.25	0	
ESTHERVILLE SUB	8253	SIMN	18.25	L	0	7/16/2015	-1.25	0	
ESTHERVILLE SUB	8253	SIMN	6.19	L	0	7/20/2015	-0.38	0	
ESTHERVILLE SUB	8253	SIMN	42.62	R	0	7/21/2015	-1.13	0	
ESTHERVILLE SUB	8253	SIMN	33.05	L	0	12/15/2015	-0.75	0	
ESTHERVILLE SUB	8253	SIMN	33.05	R	0	12/15/2015	-0.75	0	
ESTHERVILLE SUB	8253	SIMN	33.14	R	0	12/16/2015	1	0	
ESTHERVILLE SUB	8253	SIMN	40.2	L	0	12/21/2015	2	0	
ESTHERVILLE SUB	8268	SIMN	71.54	R	0	1/8/2016	2	0	
ESTHERVILLE SUB	8253	SIMN	15.21	R	0	9/12/2016	-1	0	
ESTHERVILLE SUB	8253	SIMN	32.44	R	0	1/9/2017	1.5	0	
ESTHERVILLE SUB	8253	SIMN	32.45	L	0	1/9/2017	1.75	0	
ESTHERVILLE SUB	8253	SIMN	41.5	R	0	1/30/2017	1.5	0	