



**VEHICLE FACTORS GROUP CHAIRMAN'S
FACTUAL REPORT**

**Vehicle Attachment 9 – Specifications and Recall Information for
the 2005 GMC Savana**

**MULTIPLE VEHICLE ACCIDENT
Chattanooga, TN**

HWY15MH009

(5 pages)

VINquery.com Report - 7/29/2015

VIN #	1GTFG15X551
VINquery.com Vehicle ID	29312
Model Year	2005
Make	GMC
Model	Savana
Trim	G1500 Cargo
Manufactured in	UNITED STATES
Production Seq. Number	184113

Specifications

Body Style	CARGO VAN
Engine Type	4.3L V6 OHV 12V
Transmission	4-Speed Automatic
Driveline	RWD
Tank(gallon)	31.00
Fuel Economy(City, miles/gallon)	15
Fuel Economy(Highway, miles/gallon)	20
Anti-Brake System	4-Wheel ABS
Steering Type	R&P
Seating(standard)	2
Seating(optional)	1
Length(in.)	224.10
Width(in.)	79.40
Height(in.)	81.60

Disclaimer

ALTHOUGH VINQUERY.COM CHECKS REGULARLY WITH ITS DATA SOURCES TO CONFIRM THE ACCURACY AND COMPLETENESS OF THE DATA, IT MAKES NO GUARANTY OR WARRANTY, EITHER EXPRESS OR IMPLIED, INCLUDING WITHOUT LIMITATION ANY WARRANTY OR MERCHANTABILITY OR FITNESS FOR PARTICULAR PURPOSE, WITH RESPECT TO THE DATA PRESENTED IN THIS REPORT. USER ASSUMES ALL RISKS IN USING ANY DATA IN THIS REPORT FOR HIS OR HER OWN APPLICATIONS. ALL DATA IN THIS REPORT ARE SUBJECT TO CHANGE WITHOUT NOTICE.

© 2006 - 2015 VINquery.com - Auto Databank, Inc. All rights reserved.

2005 GMC 1500 SAVANA CARGO VAN SWB

A	Longitudinal distance between the center of the front bumper and the center of the base of the windshield	35.9 in
B	Passenger Car Longitudinal distance between the center of the rear bumper and the center of the base of the backlight Station Wagon and Vans Longitudinal distance between the backlight top moulding and the front door latch pillar Pick-ups Longitudinal distance between the rearmost projection and the front door latch pillar	114.7 in
C	The maximum vertical height of the side glass	21.3 in
D	Vertical distance between the base of the side glass and the lower edge of the rocker panel	39.0 in
E	Distance between side rails or maximum width of top	57.5 in
F	Front overhang	39.8 in
G	Rear overhang	48.9 in
OL	Overall length	224.2 in
OW	Overall width	79.6 in
OH	Overall height	81.6 in
WB	Wheelbase	135.1 in
TWF	Front track width	68.2 in
TWR	Rear track width	67.8 in
CW	Curb weight	5207 lb
WD	Weight distribution (Front/Rear)	N/A

Measurements obtained in year: 03

Search Results



2005 GMC SAVANA 1500

Recalls 1 Result(s)	Investigations 0 Result(s)	Complaints 4 Result(s)
Service Bulletins 5 Result(s)		

RECALLS: Displaying 1 - 1 out of 1

— RECALL Subject : AFTERMARKET FUEL FILTERS/FUEL LEAK

Report Receipt Date: MAY 19, 2006
NHTSA Campaign Number: 06E043000
Component(s): FUEL SYSTEM, GASOLINE

All Products Associated with this Recall ▼

Details ▲

11 Associated Documents ▼

Manufacturer: HONEYWELL INTERNATIONAL, INC.

SUMMARY:

CERTAIN REPLACEMENT FUEL FILTERS, FRAM BRAND NAME P/N G3727, WITH DATE CODES X52911 THROUGH X60801 SEQUENTIALLY OR X600141 AND A MEXICO COUNTRY OR ORIGIN MARKING ON THE FUEL FILTER HOUSING MANUFACTURED FROM OCTOBER 18, 2005, THROUGH MARCH 21, 2006, SOLD FOR USE ON THE VEHICLES LISTED ABOVE AND ON CERTAIN SCHOOL BUSES. (TO SEE THE SCHOOL BUS ENGINE SIZES, CLICK ON "DOCUMENT SEARCH" AND THEN "BUS APPLICATIONS"). THE CONNECTOR ON THE FUEL FILTER WAS NOT MANUFACTURED TO HONEYWELL'S SPECIFICATION. AS A RESULT, THE O-RING MAY NOT SEAT CORRECTLY ON THE FUEL LINE.

CONSEQUENCE:

THIS CONDITION MAY CAUSE AN INADEQUATE SEAL AT THE CONNECTION, POTENTIALLY LEADING TO A FUEL LEAK. IN THE PRESENCE OF AN IGNITION SOURCE, A FIRE COULD OCCUR.

REMEDY:

HONEYWELL WILL NOTIFY OWNERS AND REPLACE THE FUEL FILTERS FREE OF CHARGE. THE RECALL BEGAN ON OCTOBER 18, 2006. OWNERS MAY CONTACT FRAM CUSTOMER SERVICE AT 1-800-890-2075 (OPTION 1).

NOTES:

THIS RECALL ONLY PERTAINS TO AFTERMARKET FRAM FUEL FILTERS AND HAS NO RELATION TO ANY ORIGINAL EQUIPMENT INSTALLED ON THE VEHICLES LISTED. CUSTOMERS MAY CONTACT THE NATIONAL HIGHWAY TRAFFIC SAFETY ADMINISTRATION'S VEHICLE SAFETY HOTLINE AT 1-888-327-4236 (TTY: 1-800-424-9153); OR GO TO [HTTP://WWW.SAFERCAR.GOV](http://www.safercar.gov).

1200 New Jersey Avenue, SE, West Building Washington DC 20590 USA 1.888.327.4236 TTY 1.800.424.9153
6.0.12.3

Email

Recalls Results by VIN - Vehicle Identification Number

Print VIN: 1GTFG15X551 

Year: 2005 Make: GMC Model: Savana 1500

Number of Open Recalls: 0

Additional Safety Information

Besides the VIN search tool you just used, NHTSA offers additional safety information based on a vehicle's make, model, and model year and not tied to any particular VIN. A search by vehicle make, model, and model year gives you access to information about technical service bulletins, NHTSA investigations, and owner complaints, as well as safety recalls on aftermarket equipment that is often not linked to a particular VIN or even to your vehicle's manufacturer.

To search NHTSA's safety information based on your vehicle's make, model, and model year, please go to the [Safety Issues section](#) and follow the instructions there.

Recall information for this manufacturer is only available going back to August 20, 1999. If your vehicle was manufactured before this date, please contact the manufacturer for possible additional recall information.

Enter another VIN here: 1GTFG15X551 

Type the text

[Privacy & Terms](#)

Submit