



## **NTSB Vehicle Photos**

**Houston, Texas**

**HWY15FH010**

(3 pages)



Vehicle Photo 1 – Overall view of the damage to the left side of the HISD school bus from the left front corner. Damage to the engine compartment, windshield and side windows can be seen.



Vehicle Photo 2 – View showing damaged HISD school bus steering components.



Vehicle Photo 3 – View showing the fractured Buick LeSabre passenger side control arm.