



Vehicle Photographs

**Rochester, IN
HWY19MH003**

(3 pages)



Photo 1. This is a view looking at the damage sustained by the left-front of the Toyota pickup.




Photo 2. This is a view looking at the damage sustained to the front of the Toyota pickup.



Photo 3. This view is looking at the damage sustained to the right-front of the Toyota pickup.



Photo 4. This is a closer view of the damage sustained to the leading edge of the hood.