



NTSB Vehicle Photos

Crozet, Virginia

HWY18MH005

(4 pages)



Vehicle Photo #1 – Overall view of the damage to the 2018 Freightliner Refuse Truck facing the left front corner.



Vehicle Photo #2 – View of the damage to the right side of the refuse truck.



Vehicle Photo #3 – View of the damage to the right side of the refuse truck from the right rear corner.



Vehicle Photo 4 – View of the detached refuse hopper of the truck as seen from the right side.



Vehicle Photo #5 – View of the damaged refuse hopper as seen from the right rear corner