



Weather Observations

Heidi Kemner
Air Safety Investigator
Eastern Region Aviation

December 16, 2017

METAR/SPECI from KTMB, Miami, Kendall-Tamiami Executive Airport (United States) .	
SA 16/12/2017 23:53->	METAR KTMB 162353Z 05004KT 10SM CLR 21/15 A3019 RMK AO2 SLP221 T02060150 10267 20206 51015=
SA 16/12/2017 22:53->	METAR KTMB 162253Z 06005KT 10SM CLR 22/15 A3017 RMK AO2 SLP216 T02170150=
SA 16/12/2017 21:53->	METAR KTMB 162153Z 09007KT 10SM SCT039 23/16 A3016 RMK AO2 SLP212 T02330156=
SA 16/12/2017 20:53->	METAR KTMB 162053Z 09011KT 10SM FEW039 25/16 A3014 RMK AO2 SLP206 T02500156 56006=
SA 16/12/2017 19:53->	METAR KTMB 161953Z 10008KT 10SM FEW039 25/16 A3015 RMK AO2 SLP208 T02500156=
SA 16/12/2017 18:53->	METAR KTMB 161853Z 09009KT 10SM BKN042 26/16 A3015 RMK AO2 SLP209 T02560161=
SA 16/12/2017 17:53->	METAR KTMB 161753Z 10005KT 10SM CLR 27/16 A3016 RMK AO2 SLP212 T02670156 10267 20139 58021=
SA 16/12/2017 16:53->	METAR KTMB 161653Z 04007KT 10SM CLR 26/14 A3020 RMK AO2 SLP224 T02560139=
SA 16/12/2017 15:53->	METAR KTMB 161553Z 03009KT 10SM CLR 24/16 A3022 RMK AO2 SLP232 T02440156=
SA 16/12/2017 14:53->	METAR KTMB 161453Z 03006KT 10SM CLR 23/16 A3022 RMK AO2 SLP234 T02280156 51016=
SA 16/12/2017 13:53->	METAR KTMB 161353Z 04006KT 10SM CLR 19/16 A3021 RMK AO2 SLP231 T01890156=
SA 16/12/2017 12:53->	METAR KTMB 161253Z 03003KT 10SM CLR 17/14 A3020 RMK AO2 SLP226 T01670144=
SA 16/12/2017 11:53->	METAR KTMB 161153Z 00000KT 10SM CLR 14/13 A3018 RMK AO2 SLP217 T01390133 10156 20106 53007=
SA 16/12/2017 10:53->	METAR KTMB 161053Z AUTO 00000KT 10SM CLR 13/12 A3016 RMK AO2 SLP211 T01280117=
SA 16/12/2017 09:53->	METAR KTMB 160953Z AUTO 00000KT 10SM CLR 13/12 A3015 RMK AO2 SLP208 T01330122=
SA 16/12/2017 08:53->	METAR KTMB 160853Z AUTO 00000KT 10SM CLR 15/13 A3016 RMK AO2 SLP211 T01500133 56008=