

## NTSB RECORD OF CONVERSATION

Investigator name: Lewis Mode: Aviation Air Safety Investigator Region: Western Pacific

Date: October 15, 2013 Person Contacted: Steve Glover Owner nVAero NTSB Accident Number: WPR13FA380

## Narrative:

During a telephone conversation with the NTSB IIC the owner of nVAreo stated that he was aware of the accident airplane, and knew that the airplane was equipped with a Continental aircraft engine. He said the Continental engine is heavier than the recommended VW engine. He further said that he had spun other KR 2 airplanes in the past, and that the spin characteristics of the "stock" airplanes (meaning plans/kit built airplanes adhering closely to build specification and engine recommendations) were similar to other low wing light airplanes. He said due to the modifications on the accident airplane, he could not speak to its spin characteristics.

The digest was reviewed with him/her during the phone call and he/she agreed with the content.



## NTSB RECORD OF CONVERSATION

The digest was reviewed with him/her during the phone call and he/she agreed with the content.