



**Critical Equipment Failure**

- Was an incident report filed?  Yes  No  N/A
- Was this a Propulsion issue? (Main Engine, Clutch, Gear Box, Shafting, Bearings, Stuffing Box)  Yes  No  N/A
- Was this a Steering issue? (Motors, Couplings, Pumps, Valves, Hoses, Jockey bars, Pins, Tillers, Rudders).  Yes  No  N/A
- Was this an Electrical Power issue? (Generator, Generator Engine, Distribution panels, Breakers).  Yes  No  N/A
- Brief description of repairs and components involved.
  - Notes: stb gen lost communication due to relay and fusible link located in control box failed electrical components where replaced with spare parts on board
- What corrective actions were taken?
  - Notes: power was regained when off-line gen was put online while repairs where being made
- Were permanent repairs completed?  Yes  No  N/A
- Suggestions on preventing this failure from occurring in the future.

**Signature**

- I agree with the above statements.  Yes  No  N/A

Completed By cecil ray frye III

11/08/2021