



Vehicle Attachment – Vehicle Examination Photographs

Delray Beach, FL

HWY23MH006

(4 pages)



Figure 1. The damage sustained to the right front of the SUV.



Figure 2. The damage sustained to the left side of the SUV.



Figure 3. Looking from the front of the engine toward where the passenger compartment would have been.



Figure 4. Looking from the rear of the engine toward the front. The tire on the left is the left side of the SUV.



Figure 5. The headlamp selector knob for the SUV.




Figure 6. The keyless ignition switch.