

Vehicle History 4/19/2021 to 4/19/2022



Labor Date	Unit	Meter at the time	Work Order	Total Hours	Proj # Warranty YES/NO	Action: Description	Task: Description	Employee or <i>Vendor</i> Entered by	Labor Comments	
4/3/22	01510	2619094	432-2021-2812	8.00	432ACPS21 NO	50: REPLACED/CHANGE D	H-A7A:PRESSURE CONTROL SWITCH- E A/C	DANO, GJERGJI BRIAN WHIPPEN	REPLACE THE #1 & 2 CAR HP & MOD SWITCHES	
	Additional notes and comments for Work Order 432-2021-2812: REPLACE THE #1 & 2 CAR HP & MOD SWITCHES									
MODL	ILATION	PRESSURE	SWITCH, #1 CA SWITCH, #2 CA I, #1 & 2 CARS,	R, MBTA	A P/N: 02696003					
4/2/22	01510	2619094	432-2022-2243	8.00	NO	55: REPAIRED	A-:AIR SYSTEM	BENITEZ, ROBERTO BRIAN WHIPPEN	T/S CHOOCHING. FOUND ATO CHECK VLAVE NG. R/R'D TEST OK	
3/30/22	01510	2619094	432-2022-2243	4.00	NO	74: SANDED/RESURFAC ED	T-A3:WHEELS	WHALEN, RYAN WILLIAM KEATING	CUT #1 AXLE	
3/29/22	01510	2619094	432-2022-2243	8.00	NO	70: WELDED/BONDED	T-A3:WHEELS	WHALEN, RYAN WILLIAM KEATING	CUT #2 & #3 AXLES	
3/28/22	01510	2619094	432-2022-2243	8.00	NO	55: REPAIRED	D-:DOORS	KILLEEN, MICHAEL THOMAS PEARSON	DEFERRED REPAIRS	
3/28/22	01510	2619094	432-2022-2243	8.00	NO	55: REPAIRED	C-ZA:MISCELLANEOUS CAR BODY REPAIRS	DEVLIN, MICHAEL THOMAS PEARSON	DEFERRED REPAIRS	
3/28/22	01510	2619094	432-2022-2243	8.00	NO	55: REPAIRED	Z-:GENERAL MISC.	DANO, GJERGJI DAVID WINFREY	DEF WORK SEE COMMENT	
3/28/22	01510	2619094	432-2022-2243	6.00	NO	55: REPAIRED	A-:AIR SYSTEM	COSTELLO, CRAIG NATALINO SILVA	SEE COMMENTS	

Additional notes and comments for Work Order 432-2022-2243:

GJERGI 1ST 3/28/22 REPAIRED HIGH RESISTANCE IN SPIN SLIDE PIN 19 CIRCUIT, REMOVED DEBRIS FROM HEATER BLOWER ASSEMBLY, TRAIN STILL CHOOCHIN WILL NEED FTS.

3/28/22

REPAIRED PEI, TESTED OK. AIR COMPRESSOR HAS LOW OFF TIME BECAUSE TRAIN IS CHOOCHING ONLY WHEN CHARGED FROM THIS CAR. R&R'D PNEUMATIC SELF LAPPER TWICE, DIDN'T HELP WITH CHOOCHING, NEEDS FURTHER T/S.

4/2/22 T/S CHOOCHING. FOUND ATO CHECK VLAVE NG. R/R'D. ADJUST AIR PRESSURES. OK CHOOCHING STOPPED. OFF TIME 5:10

3/27/22 01510	2618901	432-2022-2237	8.00	NO	30: INSPECTED	Y-M8:8-500-MILE INSPECTION	PERKINS, KEVIN JOHN JOHNSTON	TRUCK INSP
3/27/22 01510	2618901	432-2022-2237	3.50	NO	30: INSPECTED	Y-M8:8-500-MILE INSPECTION	STEVENSON, TIMOTHY JOHN JOHNSTON	CAR BODY INSP



Vehicle History 4/19/2021 to 4/19/2022



Labor Date	Unit	Meter at the time	Work Order	Total Hours	Proj #	Warranty YES/NO	Action: Description	Task: Description	Employee or <i>Vendor</i> Entered by	Labor Comments
3/27/22	01510	2618901	432-2022-2237	4.00		NO	30: INSPECTED	Y-M8:8-500-MILE INSPECTION	CHACON, HENRY JOHN JOHNSTON	AIR AND ELECTRIC
3/27/22	01510	2618901	432-2022-2237	4.00		NO	30: INSPECTED	Y-M8:8-500-MILE INSPECTION	CUNNINGHAM, NATHAN JOHN JOHNSTON	PROPULSION
3/27/22	01510	2618901	432-2022-2237	0.10		NO	28: DRAINED/EVACUATE	A-A22:PURGE TANK	STEVENSON, TIMOTHY JOHN JOHNSTON	AIR PURGE
							D D	<u> </u>		
3/27/22	01510	2618901	432-2022-2237	0.40		NO	30: INSPECTED	Y-EAI:EQUAL ACCESS INSPECTION	STEVENSON, TIMOTHY JOHN JOHNSTON	EQUAL ACCESS INSP
3/7/22	01510	2615375	432-2022-1707	4.00		NO	30: INSPECTED	H-Y:HVAC INSPECTION	MILLER, IAN BILL MACDONALD	
3/7/22	01510	2615375	432-2022-1707	2.00		NO	30: INSPECTED	H-Y:HVAC INSPECTION	MCDONOUGH, JOHN BILL MACDONALD	
3/3/22	01510	2614486	432-2022-1588	1.00		NO	55: REPAIRED	B-:BRAKE SYSTEM	HELMUTH, J SCOTT WILLIAM KEATING	RESET #1 EMERGENCY PULL
3/3/22	01510	2614486	432-2022-1588	1.00		NO	55: REPAIRED	B-:BRAKE SYSTEM	ROSEMOND, ROBERT WILLIAM KEATING	RESET #1 EMERGENCY PULL
2/28/22	01510	2613927	432-2022-1491	1.00		NO	55: REPAIRED	Z-:GENERAL MISC.	GULLOTTI-HOWARD, KR DAVID WINFREY	R/R RADIO SEE COMMENTS

Additional notes and comments for Work Order 432-2022-1491:

2-27-2022 2ND SHIFT

$\ensuremath{\text{R}}\xspace/\$\ensuremath{\text{R}}\xspace/\\xs

1/16/22 01510 2613927 432-2021-7883 8.00 432D4AIR21 NO 53: REBUILT A-AS:AIR COMPRESSOR SERVICE DANO, GJERGJI COMPLETE ANNUAL D4 AN AIR DRYER SERVICE

^{*}MOTORMANS RADIO IS MISSING FROM CAB

^{*}PICTURE WINDOW NEXT TO A1 IS BROKEN - NEEDS R&R



Vehicle History 4/19/2021 to 4/19/2022



Action: ₋abor Meter at Employee or *Vendor* Work Warranty Unit Task: Description **Labor Comments** Date YES/NO Description **Entered by** the time Order **Hours**

Additional notes and comments for Work Order 432-2021-7883:

OVERHAUL OF D4 OR D4-A COMPRESSORS WITH THE NEW GRAHAM WHITE AIR DRYERS OR VAPORLUX DRYER INSTALLED.

G:\PROCEDURES. PART LISTS. & BULLETINS\#2 CAR\D4-A COMPRESSOR

D4-A WITH NEW DRYER SERVICE PROC REV C.DOCX

CABOT D4-A NEW DRYER MAIN RECORD.DOCX

KIT PART #`S KIT-D4-RED KIT-D4-GW1

1/5/22 01510 2613927 432-2022-188 2.00 31: TROUBLESHOOT A-: AIR SYSTEM

CUNNINGHAM, NATHAN **KEVIN KELLER**

FOUND GASKET FOR INTERCOOLER PIPE

LEAKING, REPLACED.

2613926 432-2021-8241 WHIPPEN, BRIAN 12/18/21 01510 0.01 432BLODN01 NO 28: A-A22:PURGE TANK DRAINED/EVACUATE

BRIAN WHIPPEN

DRAIN AIR TANKS

Additional notes and comments for Work Order 432-2021-8241:

DRAIN AIR TANKS, IF MULTI UNIT W/O HAS BEEN USED, ADD AN A-A22 TASK TO A WORK ORDER OPEN ON THE CAR YOU'RE WORKING ON AND ADD SOME LABOF THE TASK UNTIL NOV 2021

D

BOTH CARS MUST BE DRAINED EVEN IF THERE IS ONLY ONE COMPRESSOR CAR IN THE DUECE

7/19/21 01510 2613700 432-2021-3237 4.00 432UT21 80: PERFORMED T-AS:AXLE TEST - ULTRASONIC FORESTA. STEPHEN NO

WILLIAM KEATING

UT ALL AXLES NOTE UNIT AXLE AND TRUCK S/N AND

ANY DEFECTS

Additional notes and comments for Work Order 432-2021-3237:

432-2021-3913

COMPLETE UT INSPECTION OF AXLES.

USE OLYMPUS EPOCH 600 UT UNIT IN BLUE CASE.

UT INSPECTION PROCEDURE, AXLE DRAWINGS AND FORMS ARE LOCATED IN NETWORK FOLDER:

8.00 432HDSTP21 NO

>RTLFORE\PROCEDURES, PART LISTS, & BULLETINS\UT AXLE INSPECTION PROCEDURE\

REPLACED/CHANGE COMPART

MILLER, IAN **DAVID MOONEY** REMOVE/ REPLACE **EXISTING PASSENGER** HANDSTRAPS WITH NEW

D

50:

Report Choice: DETAIL Report Type: SORTED BY DATE Units: 01510

C-K4:STANCHION- PASSENGER

Page 3 of 4

7/2/21 01510 2613700



Vehicle History 4/19/2021 to 4/19/2022



Labor Unit Date

it

Meter at the time

Work Order

Hours

Proj # Warranty YES/NO Action: Description

Task: Description

Employee or *Vendor* Entered by

Labor Comments

Additional notes and comments for Work Order 432-2021-3913:

HANDSTRAP REPLACEMENT PROGRAM

FOLLOW GRAB STRAP INSTALLATION PROCEDURE # IN-STRAP-1. IF A COLLAR IS ALREADY INSTALLED SKIP STEP 1.

Distinct # Units	Distinct # WO	Tot Hrs	Avg Hrs
1	11	109.01	4.54

Report Choice: DETAIL Report Type: SORTED BY DATE Units: 01510