



Motor Carrier Attachment:

Oregon DOT Driver/Vehicle Examination Report dated June 7, 2023

HWY23FH013

(5 pages)

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

MOTOR CARRIER MUST CERTIFY within 15 days at:
OregonTruckingOnline.com OR Fax OR mail to:
ODOT-CCD 455 Airport Road SE, Building A
Salem, OR 97301
Phone: (503)373-0982 Fax: (503)373-7481

Report Number: [REDACTED]
Inspection Date: 06/07/2023
Start: 8:57 AM PT **End:** 12:15 PM PT
Inspection Level: I - Full
HM Inspection Type: None

WAYPOINT LOGISTICS LLC
 28858 VENTURA DR
 ELKHART, IN 46517
USDOT#: 00052384
MC/MX#: 00408107
State#: 173896

Phone#: [REDACTED]
Fax#: [REDACTED]

Driver: SMITH, LINCOLN C
License#: [REDACTED] **State:** CA
Date of Birth: [REDACTED]
CoDriver:
License#: [REDACTED] **State:**
Date of Birth: [REDACTED]

Location: MARION COUNTY WILTSIE TOWYARI **MilePost:**
Highway: CHERRY ST, SALEM **Origin:** CORNING, CA
County: **Destination:** SALEM, OR **Shipper:** LEER
Bill of Lading: 25380057
Cargo: TRUCK CANOPIES

VEHICLE IDENTIFICATION

Unit	Type	Make	Year	State	Plate #	Equipment ID	VIN	GVWR	CVSA #	New CVSA #	OOS#
1	TT	FRHT	2018	IN	3194946	201948	3AKJHHDR7JSJZ6424	53,220			
2	ST	UTIL	2014	IN	SP610NHL	8402693	1UYTS2533FA336302				

BRAKE ADJUSTMENTS

Axle #	1	2	3	4	5
Right	N/A	N/A	N/A	2 1/8	2
Left	N/A	N/A	N/A	2 1/4	2 1/4
Chamber	DISC	DISC	DISC	L-30	L-30

VIOLATIONS

Vio Code	Section	Unit	OOS	Citation #	Verify	Crash	Violations Discovered
392.4A-POS	392.4A-POS	D	Y		N	N	Driver on duty and in possession of a narcotic drug / amphetamine: Driver arrested at time of crash.
395.3A2-PROPN	395.3A2-PROPN	D	N		N	N	Driving beyond 14 hour duty period (Property carrying vehicle) - Nominal Violation: 5/13/2023 driving at 14 hours 3 minutes.
395.3A2-PROPN	395.3A2-PROPN	D	N		N	N	Driving beyond 14 hour duty period (Property carrying vehicle) - Nominal Violation: 5/15/2023 driving at 14 hours 53 minutes.
395.3A2-PROPN	395.3A2-PROPN	D	N		N	N	Driving beyond 14 hour duty period (Property carrying vehicle) - Nominal Violation: 5/17/2023 driving at 14 hours and 33 minutes.
395.8E1-PC	395.8E1-PC	D	N		N	N	False Record of Duty Status - Improper use of Personal Conveyance Exception: False Log on 05/17/2023 used PC to drive 9 miles around Roseburg OR then used PC to drive 12 miles to Sutherlin OR. BOL shows drop in Eugene OR.
396.3A1	396.3A1	1	Y		U	Y	Inspection, repair and maintenance of parts & accessories: Left front hood, bumper, grill, radiator, fender, turbo and engine received major impact damage.
393.205A	393.205A	1	Y		U	Y	Wheel/rim cracked or broken: Axle 1 left side wheel bent will not hold a tire with air.
393.75A3	393.75A3	1	Y		U	Y	Tire-flat and/or audible air leak: Axle 1 left front tire blown off rim due to impact.
393.209D	393.209D	1	Y		U	Y	Steering system components worn, welded, or missing: Steering column shaft bent.

Report Prepared By:
RICHARD WITKA

Badge #:
AP0817

Copy Received By:
LINCOLN SMITH

Page 1 of 4



00052384 OR [REDACTED]

X _____

X _____

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

MOTOR CARRIER MUST CERTIFY within 15 days at:
OregonTruckingOnline.com OR Fax OR mail to:
ODOT-CCD 455 Airport Road SE, Building A
Salem, OR 97301
Phone: (503)373-0982 Fax: (503)373-7481

Report Number: [REDACTED]
Inspection Date: 06/07/2023
Start: 8:57 AM PT **End:** 12:15 PM PT
Inspection Level: 1 - Full
HM Inspection Type: None

WAYPOINT LOGISTICS LLC
 28858 VENTURA DR
 ELKHART, IN 46517
USDOT#: 00052384
MC/MX#: 00408107
State#: 173896

Phone#: [REDACTED]
Fax#: [REDACTED]

Driver: SMITH, LINCOLN C
License#: [REDACTED] **State:** CA
Date of Birth: [REDACTED]
CoDriver:
License#: [REDACTED] **State:**
Date of Birth: [REDACTED]

<u>Vio Code</u>	<u>Section</u>	<u>Unit</u>	<u>OOS</u>	<u>Citation #</u>	<u>Verify</u>	<u>Crash</u>	<u>Violations Discovered</u>
393.207A	393.207A	1	Y		U	Y	Axle positioning parts defective/missing: Axle 1 displaced and left side U-bolt sheared (1 of 2) at leaf spring to axle attachment point.
393.78	393.78	1	N		N	Y	Windshield wipers inoperative/defective: Windshield washer system destroyed.
393.60E-WS	393.60E-WS	1	N		N	Y	Windshield - Obstructed: Front drivers Windshield missing.
393.80	393.80	1	N		N	Y	No or defective rear-vision mirror: Drivers side view mirror missing.
393.203A	393.203A	1	N		N	Y	Cab door missing/broken: Drivers door severely damaged crushed shut.
393.203	393.203	1	Y		U	Y	Cab/body parts requirements violations: Driver side lower fuel tank fairing broken and protruding from truck.
396.3A1	396.3A1	1	Y		U	Y	Inspection, repair and maintenance of parts & accessories: Driveshaft between axle 2 and 3 disconnected.
393.45	393.45	1	Y		U	Y	Brake tubing and hose adequacy: Multiple brake airlines severed from axles 2 and 3 axle brake chambers.
393.75A2	393.75A2	1	Y		U	Y	Tire-tread and/or sidewall separation: Axle 2 left outside tire off bead and tread sheared approx 45% of circumference.
393.75A3	393.75A3	1	Y		U	Y	Tire-flat and/or audible air leak: Axle 3 left inside and outside tires side walls were torn and tires flat.
393.207A	393.207A	1	Y		U	Y	Axle positioning parts defective/missing: Axle 3 left side axle displaced and out of alignment approx 2.5 feet.
393.207C	393.207C	1	Y		U	Y	Leaf spring assembly defective/missing: Axle 3 left side leaf spring assembly dislodged from axle.
393.207F	393.207F	1	Y		U	Y	Air suspension pressure loss: Axle 3 left side air bag sheared from lower mount and all drive axle air bags deflated.
393.207A	393.207A	1	Y		U	Y	Axle positioning parts defective/missing: Axle 3 upper suspension connecting rod bent.
393.207A	393.207A	1	Y		U	Y	Axle positioning parts defective/missing: Axle 1 right side rear U-bolt securing springs to axle sheared.
393.201A	393.201A	2	Y		U	Y	Frame cracked / loose / sagging / broken: Trailer header board upper rail cracked and separated at side post.
		2	Y		U	Y	Frame cracked / loose / sagging / broken: Left

Report Prepared By:
RICHARD WITKA

Badge #:
AP0817

Copy Received By:
LINCOLN SMITH

Page 2 of 4



00052384 OR [REDACTED] 5

X _____

X _____

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

MOTOR CARRIER MUST CERTIFY within 15 days at:
OregonTruckingOnline.com OR Fax OR mail to:
ODOT-CCD 455 Airport Road SE, Building A
Salem, OR 97301
Phone: (503)373-0982 Fax: (503)373-7481

Report Number:
Inspection Date: 06/07/2023
Start: 8:57 AM PT End: 12:15 PM PT
Inspection Level: I - Full
HM Inspection Type: None

WAYPOINT LOGISTICS LLC
28858 VENTURA DR
ELKHART, IN 46517
USDOT#: 00052384
MC/MX#: 00408107
State#: 173896

Phone#:
Fax#:

Driver: SMITH, LINCOLN C
License#:
State: CA
Date of Birth:
CoDriver:
License#:
State:
Date of Birth:

Table with 7 columns: Vio Code, Section, Unit, OOS, Citation #, Verify, Crash, Violations Discovered. Contains two rows of violation data.

HazMat: No HM Transported. Placard: No Cargo Tank:

Special Checks: Post Crash;

State Information:
ODOMETER: 655387; Medcard Expires (mm/dd/yy): 7/29/23;

DRIVER OUT OF SERVICE NOTICE: LINCOLN SMITH may not drive until Driver not at scene. Driver's initials _____

VEHICLE OUT OF SERVICE NOTICE: Violations marked as out-of-service must be repaired before vehicle(s) can be operated.

MECHANIC CERTIFICATION: I certify that all out-of-service violations have been repaired.
Signature Of Repairer X: Facility: Date:

IF VIOLATIONS ARE NOTED, FAILURE TO RETURN MAY RESULT IN A PENALTY. If you have questions, call (503)373-0982. CARRIER CERTIFICATION: Undersigned certifies all violations have been corrected.
Signature Of Motor Carrier X: Title: Date:

Report Prepared By: RICHARD WITKA
Badge #: AP0817
Copy Received By: LINCOLN SMITH



X _____

X _____

DRIVER/VEHICLE EXAMINATION REPORT

Query Central 3.4

MOTOR CARRIER MUST CERTIFY within 15 days at:
OregonTruckingOnline.com OR Fax OR mail to:
ODOT-CCD 455 Airport Road SE, Building A
Salem, OR 97301
Phone: (503)373-0982 Fax: (503)373-7481

Report Number: [REDACTED]
Inspection Date: 06/07/2023
Start: 8:57 AM PT End: 12:15 PM PT
Inspection Level: I - Full
HM Inspection Type: None

WAYPOINT LOGISTICS LLC
28858 VENTURA DR
ELKHART, IN 46517
USDOT#: 00052384
MC/MX#: 00408107
State#: 173896

Phone#: [REDACTED]
Fax#: [REDACTED]

Driver: SMITH, LINCOLN C
License#: [REDACTED] State: CA
Date of Birth: [REDACTED]
CoDriver:
License#: [REDACTED] State:
Date of Birth: [REDACTED]

Inspection Notes

ADDED FILE #. SMS/8-7-2023Vehicle was involved in a major accident along I-5 MP240.9 NB involving fatalities. Tow company arrived on scene and caged tractor brakes and swapped a tire from axle 3 (right outside to axle 3 left outside) truck tractor received major impact damage to front and drivers side of vehicle. Left side suspension had major damage Axle 1 was displaced with broken U-bolts on each side. bent steering shaft (Axle 3 left side was displaced over 2.5 feet from mounting point). Rear driveshaft fell out from axle 3 displacement. Axle 3 suspension was chained to frame in order to be towed at time of inspection [REDACTED] tow truck driver for Wiltse.

Special Studies No Special Study Data Recorded

Report Prepared By:
RICHARD WITKA

Badge #:
AP0817

Copy Received By:
LINCOLN SMITH



X _____

X _____