| Manufacturer: | Air Tractor, Inc. | Model Number: | AT-502A |
|-------------------------|----------------------|-----------------------|---------------------------|
| Serial Number: 5 | 02A-3210 | Registration Number: | N8517Q |
| Date of Manufacture: 2 | 6 AUG 2019 | | |
| Engine installed: | | | |
| | | | |
| Manufacturer: Pratt & V | Vhitney Mode | el Number: PT6A-140AG | Serial Number: PCE-VB0070 |
| Manufacturer: Pratt & V | Vhitney Mode | el Number: PT6A-140AG | Scrial Number: PCE-VB0070 |
| Propeller installed: | | el Number: PT6A-140AG | |
| Propeller installed: | Propeller, Inc. Mode | | |

Air Tractor, Inc. 1524 Leland Snow Way, P.O. Box 485, Olney, Texas 76374 FAA Production Approval Holder

| | LIFE LIMITED AII | RCRAFT ARTICLE | ES | | | |
|---------------------------|---------------------|------------------------------|-------------|--------------------------|-------|--|
| Date | Aircraf | Aircraft Model | | Aircraft Serial Number | | |
| 26 AUG 2019 | AT- | AT-502A | | 502A-3210 | | |
| Aircraft Registration | Aircraft Total Time | raft Total Time Aircraft - F | | lights Aircraft - Starts | | |
| N8517Q | 1.0 Hours | 1.0 Hours 3 | | 1 | | |
| Nomenclature | Part N | Number | Serial ! | Number | | |
| L/H Wing -Lower Spar Cap | 210 | 94-1 | 9028 | | | |
| R/H Wing -Lower Spar Cap | 210 | 21094-2 | | 039 | | |
| Wing Attach Block - Upper | 210 | 21076-1 1095-11 | | 5-11 | | |
| Wing Attach Block - Lower | 210 | 21076-2 1095-11 | | 5-11 | | |
| | AmSafe Airbag S | System Components | | | | |
| Electronics Module Assy. | 5083 | 58-421 | A01FEB19-32 | DOM | 02/19 | |
| Inflator Assy. L/H | 5101 | 84-401 | AS26XYEYESK | DOM | 01/19 | |
| Inflator Assy. R/H | 5102 | 510226-401 | | DOM | 02/19 | |

Note: For Life Limits and replacement times, refer to the latest revision of the FAA approved Airworthiness Limitations Section of the Air Tractor Owner's Manual.

| EAR D ATE | RECORDING TACH TIME | TODAY'S FLIGHT | TOTAL TIME IN SERVICE | | of Inspections, Tests, e endorsed with Name, Ratir Repair Facility. (<i>See</i> back pa | and Cellingale Mailing |
|------------------|---|-------------------|-----------------------------|---------------------------------------|---|--|
| | | Air Tractor | FAA F | Leland Snow Wa Production Appro | v, P.O. Box 485, Olney, Texas val Holder | The second secon |
| | Date | | | Total Time | Aircraft - Flights | Engine - Starts |
| - | | | 1.0.17 | | 3 | 1 |
| accord Test F | lance with Air Torm 1009, Reviseperation. | ractor, Inc. | QCPM Section of API | ion 7: Inspection at 2016. The aircra | 0, Registration Number N851 and Testing, Production Flight aft was found to operate satisfa | Test Procedures and Flight actory and is in condition for |
| Test F safe o | form 1009, Revisementation. | ractor, inc. | dated 01 API | R 2016. The aircra | aft was found to operate satisfa | Test Procedures and Flight actory and is in condition for Engine – Starts |
| Test F safe o | orm 1009, Revision Pilot – Brent A. Date | Colvin | Pilot C | Certificate Numb | aft was found to operate satisfa | Engine – Starts |

Air Tractor, Inc., 1524 Leland Snow Way, P.O. Box 485, Olney, Texas 76374 FAA Production Approval Holder

| Date | Aircraft Make | Aircraft Model |
|------------------------|-----------------------|---------------------|
| 26 AUG 2019 | Air Tractor | AT-502A |
| Aircraft Serial Number | Aircraft Registration | Aircraft Total Time |
| 502A-3210 | N8517Q | 1.0 Hours |

I find that this aircraft Air Tractor Model AT-502A, Serial Number 502A-3210, Registration Number N8519F meets the requirements for export and have issued an <u>Export Certificate of Airworthiness on 26 AUG 2019 Export Certificate Number E473922.</u> To facilitate its delivery a temporary auxiliary fuel system has been installed in this aircraft in conformity with Air Tractor, Inc. Drawing 50280. The Export Certificate of Airworthiness is valid when the temporary installation is removed.

Terry N. Wooldridge - DMR #

| Date | Aircraft Make | Aircraft Model |
|------------------------|-----------------------|---------------------|
| 26 AUG 2019 | Air Tractor | AT-502A |
| Aircraft Serial Number | Aircraft Registration | Aircraft Total Time |
| 502A-3210 | N8517Q | 1.0 Hours |

I find that this aircraft meets the requirements for the certification requested and have issued a Special Airworthiness Certificate for the purpose of delivering or exporting the aircraft. This Special Flight Permit expires upon arrival at Primavera, MT, Brazil or on 26 FEB 2020 whichever comes first.

Terry N. Wooldridge - DMIR#

| Air | Tractor, Inc., 15 | A Production Approval Holder |
|---------------------------------------|-------------------|---|
| AD 2009-11-05 Method of Compliance | 01 JUN 2009 | Cracks In The Engine Mount This AD is not applicable due to aircraft serial number. |
| AD 2008-26-01 Method of Compliance | 28 JAN 2009 | Overturn Skid Plate Kit This AD is not applicable due to aircraft serial number. |
| AD 2006-24-10 Method of Compliance | 08 JAN 2007 | Wing Spar Lower Cap Safe life and replacement time for this aircraft is 9,800 TIS as shown in Table of this AD. |
| AD 2006-23-14 Method of Compliance | 21 DEC 2006 | Rudder and Vertical Fin Hinge Attaching Structure This AD is not applicable due to aircraft serial number. |
| AD 2004-15-15 Method of Compliance | 07 SEP 2004 | Aft Fuselage Upper Longeron This AD is not applicable due to aircraft serial number. |
| AD 98-25-01 Method of Compliance | 19 JAN 1999 | Flap Actuator Overtravel Stop This AD is not applicable due to aircraft serial number. worthiness Directives through Biweekly AD 2019-17, published for 05 AUG 2019 |

This aircraft complies with all applicable Airworthiness Directives through Biweekly AD 2019-17, published for 05 AUG 2019 through 18 AUG 2019.

Rodger Holbert - Air Tractor, Inc., 26 AUG 2019,